

Parish Paths Partnership report for February 2021

Five stiles on various footpaths in the parish have been replaced by metal gates.

My annual survey has been submitted to DCC PRoW dept. There were no major issues, but the high level of rainfall this winter has caused the usual problem of river-flow surges and erosion of the riverbank footpath (Bicton 3) north of Otterton Bridge. The situation is being monitored.

Jon Roseway