

Community Resilience Report June 2020

Yettington Vegetation

Kevin Quant, Flood Warden for Yettington, reported his concern to me regarding substantial vegetation build up in the brook opposite his house in Yettington.

I coordinated a response from Devon Clinton Estates, The Environment Agency, and subsequently the Highways Department and a positive outcome is anticipated in the coming weeks.

A build up of silt in the brook has already been removed.

Flood Warning Road Signs

All 8 road signs have now been distributed to key flood stress points.